

Additional Sample Kits

By popular demand, our Inks & Coatings team has released a complete line of sample kits:

- Lead & Cadmium Free, Series 5
 5 Colors with Tools
- Traditional Glass Stainers5 Colors with Tools
- Traditional Glass Stainers
 17 Colors (Tracing & Matting)
- Traditional Glass Stainers
 16 Colors
- Transparent
 15 Colors
- Enamels & Silver Stains
 16 Colors
- Blendable Bending
 17 Colors
- Lead & Cadmium Free, Series 5
 17 Colors
- Lead & Cadmium Free, Series 5
 17 Colors (Portrait)
- Hot Glass
 10 Colors

Order your new sample kits today!

Reusche Colors

Enamels and Silver Stains Sample Kit (2600)



419.468.5794 schillinginc.com 419.468.5794 schillinginc.com 419.468.5794 schillinginc.com



Contents

This sample kit contains:

- DX660—White (1 oz)
- 1091—**Transparent Blue #2** (1 oz)
- 7106MB—Rouge (1 oz)
- D2840—Intense Black (1 oz)
- D2862—Canary Yellow (1 oz)
- D2864—**Dark Orange** (1 oz)
- D2866—Empire Green (1 oz)
- D2870—**Resolute Blue** (1 oz)
- D26193—**Green** (1 oz)
- D2873—Bright Red (1 oz)
- D2876—Art Brown (1 oz)
- D2881—**Leaf Green** (1 oz)
- 1382—**Orange #1** (1/2 oz)
- 1384—**Yellow #3** (1/2 oz)
- 1388—**Orange Intense** (1/2 oz)
- 1390—Amber Intense (1/2 oz)
- G1795—**Gum Arabic** (1/2 oz)
- 1903—Hand Painting Medium
 (Oil Based) (1/2 oz)
- D1368—Hand Painting Medium (Water Based) (1/2 oz)

Instructions

Firing Temperature—1050-1080 F

Mixing: All colors come in a powder form and need to be mixed with a vehicle before application. Each kit includes Gum Arabic, and two different types of mixing mediums.

Mixing with Gum Arabic: Start with the color. Place a small amount onto a ground glass slab and flatten the color to approximately 1/8" thick. Sprinkle the Gum Arabic over the color, just enough to look like freshly fallen snow. You should be able to see color underneath. Add water in small amounts mixing between additions. You want a consistency similar to yogurt. The paint should be soft but retain its shape. If the color spreads out on your slab, it is too thin. More color can be added to the mixture to thicken.

Mixing with oil based or water based medium:

The recommended ratio for mixing with most mediums for hand painting is 80 % color by weight to 20 % medium by weight. Weight your color, add your medium and mix to a smooth consistency, similar to yogurt.

References

For information on various mixing mediums and techniques:

- The Art of Painting on Glass by Albinas Elskus
- Stained Glass Painting
 by Richard Millard,
 Seymour and Anita Isenberg
- Traditional Glass Painting
 DVD series by Peter McGrain

For additional information about painting on glass, please visit our lnks & Coatings website at www.schillinginc.com/inks-coatings/.

