

CATALOG NO.: 099B GT21C
VARIABLE SPEED STIRRER MOTOR CONTROL:

Connect the motor cord to the control. This plug is polarized so that it can only be plugged in one way. Make sure that the forward/reverse switch is in the center OFF position and that the motor speed knob is fully counter-clockwise. Plug the control power cord into a properly grounded polarized receptacle. Select the desired direction with the forward/reverse switch. Turn the motor speed knob clockwise to set the motor speed.

The controller is protected against overloads with a circuit breaker. If the circuit breaker trips, an overload condition might have occurred and the problem should be corrected.

Limited Warranty

See the current Glas-Col warranty policy located under the General Sales Policy on the Glas-Col website at www.glascol.com.

**Glas-Col
711 Hulman St.
Terre Haute, IN 47802-0128
TEL: 812-235-6167
FAX: 812-234-6975**