

Ideal for repairing minor damage and touch points using the powder you already have on hand. One stick for each color. Measure the perfect amount of powder with our built-in dosing chamber located inside the cap.



1 Pull the sealing plug out of the aluminum sleeve.



2 Fill the cap with powder, then pour it into the stick.



3 Press the cap back on the stick and shake for 2 mins.



4 Apply the paint and allow to dry thoroughly.



5 Close cap tightly, store and reuse for up to 3 months!



BUY ONLINE
www.EPSI.com



Smooth - EPSI Part #PTS-1
Textured - EPSI Part #PTS-2