

TROUBLESHOOTING TIPS

LEN GORDON AS-MULTI COMBO, AS-TC SERIES, FF-1094 SERIES



PROBLEM	PROBABLE CAUSE	CORRECTIVE ACTION
Pump and/or Blower Does Not Turn On	Bad Tubing, Bad Button or Bad Connection	Disconnect the hose from the air button. Using your finger, plug the hole on the bottom of the button where the tube was connected. Press the air button. If you feel any resistance while pressing the button, the air button is not defective. Check air tubing connections and try pressing the air button again.
	No Power	Reset breaker.
Pump and/or Blower Turns On without Pressing Button	Condensation in Air tube	Poke 3 small holes 4-6 inches on air tube away from control to release pressure inside the tube.
Pump or Blower Does Not Stop	Bad Air Switch	Connect a 6-12" piece of air tube and the air button. Press air button. If the unit turns off, replace air tubing.
	Bad Time Clock (For Time Clock Units)	Move the three position switch to the bottom (Off) position. Press the air button a few times to try to turn off the pump. If the pump or blower does not turn off, replace the time clock.

All controls must be installed by a licensed spa technician or electrician. If you need further assistance, please contact our Technical Service Department at 800-237-9937.



Manufacturing the Product Lines of Len Gordon

7215 Bermuda Road Las Vegas, NV 89119-4304
 Phone: 800-237-9937 Fax: 866-909-7278
 E-mail: technical@alliedinnovations.com
 Website: www.alliedinnovations.com